

ABB PAMA, PIERRE ARDOUIN

Sensi+ Maintenance kit (MTN-533-KIT) Overview

Natural Gas Quality Monitoring

ID number	ABB no.	Description	Qty
1	AA047736-01	O-RING #263 BUNA, 50A, COMP #B1006	10
2	AA047737-01	O-RING #274 BUNA, 50A, COMP #B1006	10
3	AA029159-01	O-RING #013 VITON V1000 COMPOUND	30
4	AA023379-01	SCREEN FILTER SS 1µm, OD 6.35MM, TH 0.05MM	10
5	AA021541-01	O-RING #007 TEFLON (PTFE)	20
6	AA029251-01	O-RING #016 VITON V1000 COMPOUND	60
7	AA021539-02	SCREEN FILTER SS 10µm, OD 6.35MM, TH.075MM	10
8	AA029197-01	O-RING #029 VITON V1000 COMPOUND	10
		FIBER OPTIC CAPS	10
		FIBER OPTIC COUPLER CAPS	5
		ELECTROSTATIC DISCHARGE (ESD) WRIST BAND	1
		SENSI+ GLA533 MAINTENANCE KIT SAV GUIDE	1

Comes in a hard plastic case.

Parts in Maintenance Kit are required to execute the following maintenance actions:

- Replace screen filters
- Replace Pump Manifold (SPA-533-PMPMAN)
- Replace gas Cell (SPA-533-CELL/L and /ML)
- Replace Wetted Path Assembly (SPA-533-WPA/L and /ML)



PREPARED 2026-03-24 Kenza Baspin	STATUS Approved	SECURITY LEVEL Public		
APPROVED 2026-03-31 Stefan Parmentier	DOCUMENT KIND Parts list			
OWNING ORGANIZATION ABB inc.	DOCUMENT ID. 3KXG165005R4701	REV. A	LANG. EN	PAGE 1/1