

266	DSH	DRH	MST	MRT	RST	RRT	HSH	HRH	GST	GRT	NSH	NRH	AST	ART	CSH	CRH	CST	CRT	JSH	JRH	JST	JRT
<b>Measurement</b>																						
Differential pressure	•	•	•	•																		
Gauge							•	•	•	•												
Absolute					•	•					•	•	•	•								
Multivariable															•	•	•	•	•	•	•	•
<b>Diaphragm seals</b>																						
Yes as S26 model		•		•		•		•		•		•		•		•		•		•		•
Not applicable	•		•		•		•		•		•		•		•		•		•		•	
<b>Output signal</b>																						
HART	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
HART + IEC61508 SAFETY	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
FOUNDATION Fieldbus	•	•	•	•	•	•	•	•	•	•	•	•	•	•								
PROFIBUS	•	•	•	•	•	•	•	•	•	•	•	•	•	•								
WirelessHART	•	•					•	•			•	•										
Modbus															•	•	•	•	•	•	•	•
<b>Ex-approvals</b>																						
ATEX, IECEx, FM, NEPSI, EAC	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
Inmetro	•	•					•	•			•	•										
Kosha	•	•					•	•			•	•										
<b>Accuracy</b>																						
Up to 0.025%			•						•													
Up to 0.04%	•			•	•	•	•			•			•	•			•	•			•	•
Up to 0.075%		•						•			•				•	•				•	•	
Up to 0.1%													•									
<b>Temperature limits</b>																						
<b>Process</b>																						
- 40 to 121 °C																						
- 40 to 250 °F	•		•		•		•				•				•		•		•		•	
- 50 to 121 °C																						
- 58 to 250 °F										•				•								
- 100 to 375 °C		•		•		•		•		•		•		•		•		•		•		•
- 148 to 707 °F		•		•		•		•		•		•		•		•		•		•		•
<b>Storage</b>	- 50 to 85 °C (- 58 to 185 °F)																					

261	AC	AG	AJ	AM	AN	AR	AS	GC	GG	GJ	GM	GN	GR	GS
<b>Measurement</b>														
Gauge								•	•	•	•	•	•	•
Absolute	•	•	•	•	•	•	•							
<b>Diaphragm seals</b>														
Yes as S26 model	•	•	•	•	•	•	•	•	•	•	•	•	•	•
Not applicable								•						•
<b>Ex-approvals</b>														
ATEX, IECEx, FM, CSA, NEPSI, EAC	•	•	•	•	•	•	•	•	•	•	•	•	•	•
<b>Accuracy</b>														
Up to 0.1%	•	•	•	•	•	•	•	•	•	•	•	•	•	•
<b>Temperature limits</b>														
<b>Process</b>														
- 30 to 180 °C														
- 22 to 356 °F	•	•	•	•	•			•	•	•	•	•		
- 50 to 120 °C														
- 58 to 248 °F								•						•
- 40 to 375 °C														
- 40 to 707 °F								•						•
<b>Storage</b>	- 50 to 85 °C (- 58 to 185 °F)													